


## Appendix D. Product Photos






TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : D1 of D2
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01

Report No.: FA090307-01A



Report No.: FA090307-01A

## **Antenna Location:**



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : D2 of D2
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01



Report No.: FA090307-01A

## Appendix E. **Test Setup Photos**



Primary Landscape (5 mm Gap)

**Primary Portrait (5 mm Gap)** 



Secondary Portrait (5 mm Gap)



Bottom of DUT (5 mm Gap)

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700

Page Number : E1 of E1 Report Issued Date: Nov. 04, 2010

Report Version : Rev. 01