



Report No.: FG090307-01A

Appendix B. Setup Photographs

<Radiated Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : B1 of B2
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01





Report No.: FG090307-01A



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7H-N700 Page Number : B2 of B2
Report Issued Date : Nov. 04, 2010
Report Version : Rev. 01