


### Report No.: FD9D1639-03

# **Setup Photographs**

# <Conducted Emission> Mode 5



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7N-0610 Page Number : 1 of 4
Report Issued Date : Mar. 09, 2010
Report Version : Rev. 01





**Report No. : FD9D1639-03** 



Side View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7N-0610

Page Number : 2 of 4

Report Issued Date : Mar. 09, 2010

Report Version : Rev. 01





Report No.: FD9D1639-03

## <Radiated Emission>

### Mode 5



Front View



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7N-0610

Page Number : 3 of 4 Report Issued Date: Mar. 09, 2010 : Rev. 01

Report Version





**Report No. : FD9D1639-03** 



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: X7N-0610

Page Number : 4 of 4

Report Issued Date : Mar. 09, 2010

Report Version : Rev. 01