

## **ARRAY SOLUTIONS**

2611 N. Beltline Rd Suite 109 Sunnyvale, TX 75182

214 954 7140 office 214 954 7142 fax

Info@arraysolutions.com

Monday, August 11, 2014

To Inspecting EA Engineer,

Thank you for pointing out our non-compliance to the 50Mhz specification of this OM2000+ amplifier. We have modified the output harmonic filter tank circuitry to more then meet the specification. All production units sold in the USA will have this added filtering.

I am have uploaded the new measurement exhibits for your review.

I attest these measurements are accurate.

Best Regards,

John Terleski President