

The Broadband Wireless Access Company

July 18, 2012

InfiNet Malta Limited 222 Merchants Street, Valletta VLT1170 Malta

RE: FCC ID X8Q-SMC-362322

To Jyun-Cheng Chen, JC.Chen@fcc.gov

Concerning your request for clarification (correspondence reference number 128076, form 731 confirmation number TC725151, date of original email 07/06/2012) regarding DFS disabling possibility ("DFS without Radar Detection" menu item shown in the tune-up procedure document) we would like to stress the above mentioned DFS mode does utilize Dynamic Frequency Selection algorithm, but not Radar detection as there is no such requirement defined for this frequency band in FCC rules Part 90Z.

DFS cannot be disabled by the user on the units shipped to the US.

Should you have any further questions please feel free contact me.

Sincerely, Andrey Koynov CTO

