

## REVISION HISTORY

Revision 0000-P2 -- EEPROM for BCM2042Al set switcher VDDA output to 1.85v, and using VDDA for on chip LDO input Revision 0020-P1 -- Put additional resistor R22 to avoid Xtal startup issue update the components value on "pi" low pass filter for 2nd and 3rd harmonic reduction

BROADCOM

**Broadcom Proprietary & Confidential** 





