

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL : 86-0512-5790-0158 FAX : 86-0512-5790-0958 FCC ID : XAPGM5PLUS Page Number : B1 of B2
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBTVersion1.1

Report No.: FR611201-01A




Report No. : FR611201-01A


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : B2 of B2
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBTVersion1.1