
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 5



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : A1 of A3
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3

Report No.: FC611201-01

<Radiated Emission>

Mode 3

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : A2 of A3
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01


Report Template No.: BU5-FD15B Version 1.3

Report No.: FC611201-01


Report No. : FC611201-01

Mode 5

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : A3 of A3
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3