

Appendix C. Setup Photographs

<Conducted Emission>

Mode 1



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C1 of C2
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWLVersion1.2

Report No.: FR611201-01C







<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XAPGM5PLUS Page Number : C2 of C2
Report Issued Date : Apr. 27, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWLVersion1.2

Report No.: FR611201-01C