
8. SETUP PHOTOS

Conducted Emission Measurements With AC/DC Adaptor



With PC




Field Strength of Spurious



X-Orientation



Y-Orientation





Z-Orientation



EUT w/ PC Connected