## **Chris Harvey**

To: charvey@ieee.org

Subject: SJ system, FCC ID: XBWSC-100T, Assessment NO.: AN09T9189, Notice#3

Attachments: [SC-100T] MANUAL.pdf; [SC-100T] Test report.pdf

Hi charvey

Please explain why the conducted power measurements in the revised report are so much lower than the peak power measurements in the original report.

- -I require in company and lower output power
- -Because it is to satisfy MPE

There is no documentation in the test report of the measurement using the required substitution method of EIA/TIA-603. This revised report now documents ERP of 0.851W, 0.837W and 0.743W for the 3 measured channels, but provides no information as to how these ERP values have been obtained.

- Test report attached

The responses to my first notice item #9 and my second notice item #2 have not been addressed by you.

#9: This equipments offer with antenna and manual attached


#2: Test report attached

Must take advantage of certificate really today.

I do not go to the house until certificate is published and will wait.

Please, ask.

thanks











한메일과 함께하는

실종가족 찾기 캠페인



이 름 | **기한서 (현재 64세)** 실종일자 | 2009년 2월 23일 실종장소 | 서울 종로구 창신동

장 + 정신장애 2급,치이없음

