Test report No. : 31KE0265-HO-01-A-R1

Page

: 26 of 28 : December 8, 2011 : December 12, 2011 : XBXRA102 **Issued date** Revised date FCC ID

APPENDIX 3: Photographs of test setup

Conducted Emission



Photo 1




Photo 2

UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

: 31KE0265-HO-01-A-R1 Test report No.

Page

: 27 of 28 **Issued date** : December 8, 2011 Revised date FCC ID : December 12, 2011 : XBXRA102

Radiated Emission



Photo 1




Photo 2

UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 31KE0265-HO-01-A-R1

Page : 28 of 28

Issued date : December 8, 2011
Revised date : December 12, 2011
FCC ID : XBXRA102

Worst Case Position (Horizontal: Z-axis/ Vertical: X-axis)

X-axis



Y-axis



Z-axis



Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124