Test report No. : 29GE0111-HO-01-A-R1

Page : 13 of 34

Issued date : May 28, 2009


Revised date : June 15, 2009

FCC ID : XBXBC5849501

APPENDIX 1: Photographs of test setup

Conducted Emission

Front







UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 29GE0111-HO-01-A-R1

Page : 14 of 34

Issued date : May 28, 2009


Revised date : June 15, 2009

FCC ID : XBXBC5849501

Spurious Emission (Radiated)

Front





UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


Test report No. : 29GE0111-HO-01-A-R1


Page : 15 of 34
Issued date : May 28, 2009
Revised date : June 15, 2009
FCC ID : XBXBC5849501

Worst Case Position (Horizontal: Z-axis/ Vertical: X-axis)

X-axis







UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124