Technical Description

For our product, the firmware in the factory has been fixed in to chip, can't change, and the Software/firmware decided the RF parameters (i.e. allowed channels and Max EIRP Tx Power). Tx Power is limited to the Maximum EIRP certified by the grant.

It is not possible for third parties to load device drivers that could modify the RF parameters, country of operation or other parameters which impact device compliance.

Any third parties have NO capability to operate a US sold device on any other regulatory domain, frequencies, or in any manner that is in violation of the certification.