Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory


Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Annex to Test report no.: 2-4299-01-02/06 Date: 2006-08-24 Page 19 of 29

6 Annex B: Photographs of Test site

Photo 1 (Radiated Emissions):




Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Annex to Test report no.: 2-4299-01-02/06 Date: 2006-08-24 Page 20 of 29

Photo 2 (Radiated Emissions):



Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory

Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Annex to Test report no.: 2-4299-01-02/06 Date: 2006-08-24 Page 21 of 29

Photo 3 (Radiated Emissions):




Untertürkheimer Str. 6-10, 66117 Saarbruecken RSC-Laboratory


Phone: +49 (0) 681 598-0 Phone: +49 (0) 681 598-0 Fax: -9075 Fax: -9075



Annex to Test report no.: 2-4299-01-02/06 Date: 2006-08-24 Page 22 of 29

Photo 4 (Conducted Emissions):







Fax: -9075

Fax: -9075

Annex to Test report no.: 2-4299-01-02/06 Date: 2006-08-24 Page 23 of 29

Photo 5 (Conducted Emissions):

