

Report No.: HK09050758-3



Date: 29.MAY.2009 12:47:11


Report No.: HK09050758-3



Date: 29.MAY.2009 12:40:40

Report No.: HK09050758-3

Span 150 kHz



15 kHz/


Date: 29.MAY.2009 12:51:01

Center 927.25 MHz

Report No.: HK09050175-3

Stop 910 MHz

H3A



800 kHz/

Date: 29.MAY.2009 15:09:33


-60

Start 902 MHz

Report No.: HK09050175-3

Н3В






Date: 29.MAY.2009 15:11:13

Report No.: HK09050175-3

Stop 928 MHz

**H3C** 




800 kHz/

Date: 29.MAY.2009 15:12:16


Start 920 MHz

Report No.: HK09050758-3



Date: 29.MAY.2009 15:22:05

Report No.: HK09050758-3




5 s/

Date: 1.JUN.2009 14:35:23

Center 902.75 MHz

Report No.: HK09050758-3






Date: 30.MAY.2009 12:14:11

Report No.: HK09050758-3

Stop 1 GHz






99.9 MHz/

Date: 29.MAY.2009 16:32:22

Start 1 MHz

Report No.: HK09050758-3







920 MHz/ Stop 10 GHz Start 800 MHz


Date: 29.MAY.2009 16:30:42

-- 50-

-60

Report No.: HK09050758-3






Date: 29.MAY.2009 16:41:55

Report No.: HK09050758-3






Date: 29.MAY.2009 16:41:14

Report No.: HK09050758-3






Date: 29.MAY.2009 16:14:54

Report No.: HK09050758-3






Date: 29.MAY.2009 16:16:26

Report No.: HK09050758-3






Date: 30.MAY.2009 10:20:34

Report No.: HK09050758-3





Date: 29.MAY.2009 16:10:57