
Report No.: HK09050758-3

Stop 1 GHz






99.9 MHz/

Date: 29.MAY.2009 16:32:22


Start 1 MHz

Report No.: HK09050758-3










Date: 29.MAY.2009 16:30:42

Report No.: HK09050758-3






Date: 29.MAY.2009 16:41:55

Report No.: HK09050758-3






Date: 29.MAY.2009 16:41:14

Report No.: HK09050758-3

Stop 1 GHz






99.9 MHz/

Date: 29.MAY.2009 16:14:54

Start 1 MHz

Report No.: HK09050758-3






Date: 29.MAY.2009 16:16:26

Report No.: HK09050758-3






Date: 30.MAY.2009 10:20:34

Report No.: HK09050758-3





Date: 29.MAY.2009 16:10:57