Appendix A. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XF6-RS9110N1103 Page Number : A1 of A3
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01


Report No.: FR472246A

Report Template No.: BU5-FR15CWL Version 1.0


<Radiated Emission>

Y Plane for WLAN 2.4GHz

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XF6-RS9110N1103 Page Number : A2 of A3
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01


Report No.: FR472246A

Report Template No.: BU5-FR15CWL Version 1.0


C RF Test Report No. : FR472246A

X Plane for WLAN 5GHz

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XF6-RS9110N1103 Page Number : A3 of A3
Report Issued Date : Sep. 05, 2014
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.0