Client	MMB Research Inc.	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2015	Canada




Figure 1: Radiated emissions setup – photo 1

Page 1 of 6 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc.	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2015	Canada




Figure 2: Radiated emission setup – photo 2

Page 2 of 6 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc.	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2015	Canada




Figure 3: Radiated emission setup – photo 3

Page 3 of 6 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc.	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2015	Canada



Figure 4: Antenna port conducted emission - photo

Page 4 of 6 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc.	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2015	Canada



Figure 5: Power line conducted emission setup – photo 1

Page 5 of 6 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc.	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2015	Canada




Figure 6: Power line conducted emission setup – photo 2

Page 6 of 6 Report issue date: 7/19/2016 Report No. 7169000901-0000