Client	MMB Research Inc	
Product	Grissom	TÜV
Standard(s)	RSS 247 Issue 1:2015 / FCC Part 15 Subpart 15.247:2016	Canada




Figure 1: EUT internal view – top

Page 1 of 4 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc	
Product	Grissom	TÜV
Standard(s)	RSS 247 Issue 1:2015 / FCC Part 15 Subpart 15.247:2016	Canada



Figure 2: EUT internal view – rear

Page 2 of 4 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc	
Product	Grissom	SUD
Standard(s)	RSS 247 Issue 1:2015 / FCC Part 15 Subpart 15.247:2016	Canada




Figure 3: Internal view, PCB top

Page 3 of 4 Report issue date: 7/19/2016 Report No. 7169000901-0000

Client	MMB Research Inc	
Product	Grissom	TÜV
Standard(s)	RSS 247 Issue 1:2015 / FCC Part 15 Subpart 15.247:2016	Canada



Figure 4: Internal view, PCB rear

Page 4 of 4 Report issue date: 7/19/2016 Report No. 7169000901-0000