Client	MMB Research Inc.	
Product	Lakota	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2016	Canada



Figure 1: Radiated emissions setup – photo 1

Page 1 of 5 Report issue date: 5/2/2016 GEMC File #: XFF-LKT00 23447R0

Client	MMB Research Inc.	
Product	Lakota	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2016	Canada




Figure 2: Radiated emission setup – photo 2

Page 2 of 5 Report issue date: 5/2/2016 GEMC File #: XFF-LKT00 23447R0

Client	MMB Research Inc.	
Product	Lakota	TÜV
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2016	Canada



Figure 3: Radiated emission setup – photo 3

Page 3 of 5 Report issue date: 5/2/2016 GEMC File #: XFF-LKT00 23447R0

Client	MMB Research Inc.	
Product	Lakota	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2016	Canada



Figure 4: Radiated emission setup – photo 4

Page 4 of 5 Report issue date: 5/2/2016 GEMC File #: XFF-LKT00 23447R0

Client	MMB Research Inc.	
Product	Lakota	SUD
Standard(s)	RSS 247 Issue1:2015 / FCC Part 15 Subpart 15.247:2016	Canada




Figure 5: Antenna port conducted emission - photo

Page 5 of 5 Report issue date: 5/2/2016 GEMC File #: XFF-LKT00 23447R0