



## Appendix D. Product Photos





TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XGMN37B Page Number : D1 of D2
Report Issued Date : Oct. 30, 2009
Report Version : Rev. 01

Report No.: FA971421-01B



Report No.: FA971421-01B

## **Antenna Location:**



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XGMN37B Page Number : D2 of D2
Report Issued Date : Oct. 30, 2009
Report Version : Rev. 01



## Appendix E. Test Setup Photos



Face of the DUT with Phantom 1.5 cm Gap

Bottom of the DUT with Phantom 1.5 cm Gap

Report No.: FA971421-01B

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XGMN37B

Page Number : E1 of E1 Report Issued Date: Oct. 30, 2009

Report Version : Rev. 01