

attn: Reviewing Engineer

Federal Communications Commission

7435 Oakland Mills Road Columbia, MD 21046

## To Whom It May Concern:

The DNL920, FCC ID: XGO-DNL9XX and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3) "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- This device may not cause harmful interference and
- (2) This device must accept any interference received, including interference that may cause undesired operation."

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

Sincerely,

Haim Rifa

QAManager OAManager

€Sourier Systems Ltd.