

Date: 21 September 21, 2009

Federal Communications Commission Authorization and Evaluation Division Attention Reviewing Engineer

The following radio devices include a mini USB port, however at this time the mini USB port is not functional:

- 1. Dat.aNet RH/Temp Logger M/N DNL920 FCC ID: XGO-DNL9XX
- 2. DataNet Logger M/N DNL910 FCC ID: XGO-DNL9XX

The above units will be tested for Sub-part B connected to a PC/Laptop when the mini USB port becomes functional.

Sincerely

Haim Bila/ QA Manager

Fourier System Ltd.