From: Emc [emc@itl.co.il]

Sent: Monday, September 21, 2009 10:02 AM

To: TEI@TimcoEngr

Subject: FOURIER SYSTEMS LTD. - FCC ID: XGO-DNR900 Timco Job Num

ber JOB 2149IC9

Attachments: DNL910 DNL920 Mini USB Port Explanation.pdf

## Hello,

- 1. Please be advised that a DoC will be performed for this unit. Sub-part B testing with the unit connected to a laptop have been performed.
- 2. Concerning "PLEASE NOTE: THIS ALSO APPLIES TO XGO-DNL0XXX,

XGO-DNR800, AND XGO-DNL8XX", Only the units under FCC ID: XGO-DNK9XX have a mini USB port which at this time is non functional. The appropriate testing and DoC will be performed when the mini USB port becomes functional. Please see the attached letter from Fourier.

3. Please let us know if you need any additional information.

Thank you

**David Shidlowsky** 

**Technical Writer** 

**EMC Laboratory** 

ITL (Product Testing) Ltd.

Lod/Kfar Bin Nun

Israel

Tel: +972-8-915-3100 Ext 213

Fax: +972-8-915-3101

Email: davids@itl.co.il/emc@itl.co.il

http://www.itl.co.il

This e-mail message may contain privileged or confidential information. If you are not the intended recipient, you may not disclose, use, disseminate, distribute, copy or rely upon this message or attachment in any way. If you received this e-mail message in error, please return by forwarding the message and its attachments to the sender.