Test report No. : 29IE0011-HO-01-C

Page : 15 of 40

Issued date : June 17, 2009

FCC ID : XGP-BPAD06


APPENDIX 1: Photographs of test setup

Conducted Emission

Photo 1







UL Japan, Inc. Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124


: 29IE0011-HO-01-C Test report No. : 16 of 40

Page


: June 17, 2009 : XGP-BPAD06 Issued date FCC ID

Radiated Spurious Emission

Photo 1







UL Japan, Inc. **Head Office EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone Facsimile : +81 596 24 8116 : +81 596 24 8124

: 29IE0011-HO-01-C Test report No. : 17 of 40

Page

Issued date : June 17, 2009 FCC ID : XGP-BPAD06

Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)

Cradle X-axis









4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

: +81 596 24 8116 Telephone Facsimile : +81 596 24 8124