Test report No. : 29IE0011-HO-01-A

Page : 15 of 48 Issued date : June 17, 2009 FCC ID : XGP-BPAD06


## **APPENDIX 1: Photographs of test setup**

## **Conducted Emission**

## Photo 1



Photo 2



## UL Japan, Inc.

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 29IE0011-HO-01-A

Page : 16 of 48 : June 17, 2009 : XGP-BPAD06 Issued date FCC ID

# **Radiated Spurious Emission**







Photo 2



# UL Japan, Inc.

**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124

Test report No. : 29IE0011-HO-01-A

Page : 17 of 48 Issued date : June 17, 2009 FCC ID : XGP-BPAD06

## Worst Case Position (Horizontal: X-axis/ Vertical: Y-axis)









**Head Office EMC Lab.** 

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116 Facsimile : +81 596 24 8124