
1. External Photograph of EUT

Brand Name: NetComm / Model Name: 3G39W-V & 3G39W-I

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Brand Name: NetComm / Model Name: 3G39W-V & 3G39W-I

Marketing Name: HSPA+ Wi-Fi Router

Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 2 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: NetComm / Model Name: 3G39W-V & 3G39W-I

Marketing Name: HSPA+ Wi-Fi Router

Report No.: EP102734

List of Accessory:

Specification of Accessory		
IAC: Adapter	Brand Name	AMIGO
	Model Name	AMS3-1201500FU
IWWAN Module	Brand Name	Huawei
	Model Name	EM820U
IWI AN Module	Brand Name	Ralink
	Model Name	RT3052F

Remark: For accessories equipped with this EUT, please refer to the following photos.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 3 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Brand Name: NetComm / Model Name: 3G39W-V & 3G39W-I

Marketing Name: HSPA+ Wi-Fi Router

Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 4 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Brand Name: NetComm / Model Name: 3G39W-V & 3G39W-I

Marketing Name: HSPA+ Wi-Fi Router

Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 5 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01