

Report No.: FR250708

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC40WV Page Number : B1 of B2
Report Issued Date : Sep. 06, 2012
Report Version : Rev. 01




Report No.: FR250708

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC40WV Page Number : B2 of B2
Report Issued Date : Sep. 06, 2012
Report Version : Rev. 01