
3. Internal Photograph of EUT

Brand Name: NetComm Wireless / Model Name: NTC-6908-02 / Marketing Name: M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 6 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908

: 7 of 15 Page Number Report Issued Date : Oct. 31, 2012 Report Version : Rev. 02


Report No.: EP291705

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 8 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02




Brand Name: NetComm Wireless / Model Name: NTC-6908-02 / Marketing Name: M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908

Page Number : 9 of 15 Report Issued Date : Oct. 31, 2012 Report Version : Rev. 02




SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 10 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 11 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 12 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 13 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908 Page Number : 14 of 15
Report Issued Date : Oct. 31, 2012
Report Version : Rev. 02



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC6908 IC: 8847A-NTC6908