


Date: 6.JUN.2014 22:46:59

#### 26dB Bandwidth Plot on Channel 19175




Date: 6.JUN.2014 22:47:35

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 101 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 5MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 18625



Date: 6.JUN.2014 22:37:24

#### 26dB Bandwidth Plot on Channel 18625




Date: 6.JUN.2014 22:38:03

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 102 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:43:59


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 22:44:38


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 103 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:47:16

#### 26dB Bandwidth Plot on Channel 19175




Date: 6.JUN.2014 22:47:55

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 104 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 10MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 18650



Date: 6.JUN.2014 22:53:36

#### 26dB Bandwidth Plot on Channel 18650




Date: 6.JUN.2014 22:54:13

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 105 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:00:10


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 23:00:47


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 106 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:03:27

#### 26dB Bandwidth Plot on Channel 19150




Date: 6.JUN.2014 23:04:04

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 107 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 10MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 18650



Date: 6.JUN.2014 22:53:54

#### 26dB Bandwidth Plot on Channel 18650




Date: 6.JUN.2014 22:54:33

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 108 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:00:28


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 23:01:06


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 109 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:03:44

## 26dB Bandwidth Plot on Channel 19150




Date: 6.JUN.2014 23:04:23

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 110 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 15MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 18675



Date: 6.JUN.2014 23:10:05

#### 26dB Bandwidth Plot on Channel 18675




Date: 6.JUN.2014 23:10:41

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 111 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:16:38


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 23:17:15


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 112 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:19:56

## 26dB Bandwidth Plot on Channel 19125




Date: 6.JUN.2014 23:20:33

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 113 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 15MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 18675



Date: 6.JUN.2014 23:10:22

#### 26dB Bandwidth Plot on Channel 18675




Date: 6.JUN.2014 23:11:01

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 114 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:16:56


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 23:17:34


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 115 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:20:13

## 26dB Bandwidth Plot on Channel 19125




Date: 6.JUN.2014 23:20:52

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 116 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 20MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 18700



Date: 6.JUN.2014 23:26:34

## 26dB Bandwidth Plot on Channel 18700




Date: 6.JUN.2014 23:27:11

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 117 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:33:09


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 23:33:46


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 118 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:36:27

## 26dB Bandwidth Plot on Channel 19100




Date: 6.JUN.2014 23:37:04

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 119 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 2 BW / Mod.: 20MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 18700



Date: 6.JUN.2014 23:26:52

#### 26dB Bandwidth Plot on Channel 18700




Date: 6.JUN.2014 23:27:31

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 120 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:33:27


## 26dB Bandwidth Plot on Channel 18900



Date: 6.JUN.2014 23:34:05


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 121 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:36:45

## 26dB Bandwidth Plot on Channel 19100




Date: 6.JUN.2014 23:37:24

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 122 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 1.4MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 26047



Date: 6.JUN.2014 22:04:06

#### 26dB Bandwidth Plot on Channel 26047




Date: 6.JUN.2014 22:04:43

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 123 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:10:40


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 22:11:17


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 124 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 13:45:13

#### 26dB Bandwidth Plot on Channel 26683




Date: 8.JUN.2014 13:45:51

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 125 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


**Band**: LTE Band 25 **BW / Mod.**: 1.4MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 26047



Date: 6.JUN.2014 22:04:24

#### 26dB Bandwidth Plot on Channel 26047




Date: 6.JUN.2014 22:05:02

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 126 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:10:58


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 22:11:37


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 127 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 13:45:31

#### 26dB Bandwidth Plot on Channel 26683




Date: 8.JUN.2014 13:45:31

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 128 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 3MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 26055



Date: 6.JUN.2014 22:20:36

#### 26dB Bandwidth Plot on Channel 26055




Date: 6.JUN.2014 22:21:13

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 129 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:27:10


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 22:27:47


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 130 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 13:51:58

#### 26dB Bandwidth Plot on Channel 26675




Date: 8.JUN.2014 13:52:36

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 131 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 3MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 26055



Date: 6.JUN.2014 22:20:54

#### 26dB Bandwidth Plot on Channel 26055




Date: 6.JUN.2014 22:21:33

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 132 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:27:28


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 22:28:06


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 133 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 13:52:16

#### 26dB Bandwidth Plot on Channel 26675




Date: 8.JUN.2014 13:52:56

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 134 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 5MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 26065



Date: 6.JUN.2014 22:37:07

#### 26dB Bandwidth Plot on Channel 26065




Date: 6.JUN.2014 22:37:44

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 135 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:43:41


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 22:44:18


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 136 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 13:58:43

## 26dB Bandwidth Plot on Channel 26665




Date: 8.JUN.2014 13:59:20

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 137 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 5MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 26065



Date: 6.JUN.2014 22:37:24

#### 26dB Bandwidth Plot on Channel 26065




Date: 6.JUN.2014 22:38:03

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 138 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 22:43:59


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 22:44:38


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 139 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 13:59:01

## 26dB Bandwidth Plot on Channel 26665




Date: 8.JUN.2014 13:59:01

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 140 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 10MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 26090



Date: 6.JUN.2014 22:53:36

#### 26dB Bandwidth Plot on Channel 26090




Date: 6.JUN.2014 22:54:13

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 141 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:00:10


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 23:00:47


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 142 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 14:05:28

## 26dB Bandwidth Plot on Channel 26640




Date: 8.JUN.2014 14:06:06

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 143 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 10MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 26090



Date: 6.JUN.2014 22:53:54

#### 26dB Bandwidth Plot on Channel 26090




Date: 6.JUN.2014 22:54:33

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 144 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:00:28


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 23:01:06


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 145 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 14:05:46

## 26dB Bandwidth Plot on Channel 26640




Date: 8.JUN.2014 14:06:26

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 146 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 15MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 26115



Date: 6.JUN.2014 23:10:05

#### 26dB Bandwidth Plot on Channel 26115




Date: 6.JUN.2014 23:10:41

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 147 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:16:38


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 23:17:15


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 148 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 14:12:14

## 26dB Bandwidth Plot on Channel 26615




Date: 8.JUN.2014 14:12:52

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 149 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


**Band**: LTE Band 25 **BW / Mod**.: 15MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 26115



Date: 6.JUN.2014 23:10:22

#### 26dB Bandwidth Plot on Channel 26115




Date: 6.JUN.2014 23:11:01

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 150 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:16:56


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 23:17:34


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 151 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 14:12:32

## 26dB Bandwidth Plot on Channel 26615




Date: 8.JUN.2014 14:13:12

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 152 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 20MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 26140



Date: 6.JUN.2014 23:26:34

## 26dB Bandwidth Plot on Channel 26140




Date: 6.JUN.2014 23:27:11

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 153 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:33:09


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 23:33:46


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 154 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 14:18:55

## 26dB Bandwidth Plot on Channel 26590




Date: 8.JUN.2014 14:19:32

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 155 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 25 BW / Mod.: 20MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 26140



Date: 6.JUN.2014 23:26:52

#### 26dB Bandwidth Plot on Channel 26140




Date: 6.JUN.2014 23:27:31

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 156 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:33:27


## 26dB Bandwidth Plot on Channel 26340



Date: 6.JUN.2014 23:34:05


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 157 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 14:19:13

## 26dB Bandwidth Plot on Channel 26590




Date: 8.JUN.2014 14:19:51

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 158 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 1.4MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 19957



Date: 6.JUN.2014 23:49:34

#### 26dB Bandwidth Plot on Channel 19957




Date: 6.JUN.2014 23:50:11

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 159 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:56:07


#### 26dB Bandwidth Plot on Channel 20175



Date: 6.JUN.2014 23:56:44


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 160 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:59:25

#### 26dB Bandwidth Plot on Channel 20393




Date: 7.JUN.2014 00:00:02

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 161 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 1.4MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 19957



Date: 6.JUN.2014 23:49:51

#### 26dB Bandwidth Plot on Channel 19957




Date: 6.JUN.2014 23:50:30

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 162 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:56:25


#### 26dB Bandwidth Plot on Channel 20175



Date: 6.JUN.2014 23:57:04


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 163 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 6.JUN.2014 23:59:43

#### 26dB Bandwidth Plot on Channel 20393




Date: 7.JUN.2014 00:00:22

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 164 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 3MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 19965



Date: 7.JUN.2014 00:06:04

#### 26dB Bandwidth Plot on Channel 19965




Date: 7.JUN.2014 00:06:41

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 165 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:12:38


#### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 00:13:15


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 166 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:15:55

#### 26dB Bandwidth Plot on Channel 20385




Date: 7.JUN.2014 00:16:32

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 167 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 3MHz / 16QAM

## 99% Occupied Bandwidth Plot on Channel 19965



Date: 7.JUN.2014 00:06:21

#### 26dB Bandwidth Plot on Channel 19965




Date: 7.JUN.2014 00:07:00

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 168 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:12:55


#### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 00:13:34


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 169 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:16:13

#### 26dB Bandwidth Plot on Channel 20385




Date: 7.JUN.2014 00:16:52

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 170 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 5MHz / QPSK

## 99% Occupied Bandwidth Plot on Channel 19975



Date: 7.JUN.2014 00:22:36

#### 26dB Bandwidth Plot on Channel 19975




Date: 7.JUN.2014 00:23:13

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 171 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:29:10


#### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 00:29:47


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 172 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:32:28

### 26dB Bandwidth Plot on Channel 20375




Date: 7.JUN.2014 00:33:05

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 173 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 5MHz / 16QAM

### 99% Occupied Bandwidth Plot on Channel 19975



Date: 7.JUN.2014 00:22:53

#### 26dB Bandwidth Plot on Channel 19975




Date: 7.JUN.2014 00:23:32

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 174 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:29:28


#### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 00:30:06


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 175 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 00:32:46

### 26dB Bandwidth Plot on Channel 20375




Date: 7.JUN.2014 00:33:24

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 176 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 10MHz / QPSK

### 99% Occupied Bandwidth Plot on Channel 20000



Date: 7.JUN.2014 00:58:46

#### 26dB Bandwidth Plot on Channel 20000




Date: 7.JUN.2014 00:59:24

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 177 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:05:21


### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 01:05:58


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 178 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:08:39

### 26dB Bandwidth Plot on Channel 20350




Date: 7.JUN.2014 01:09:16

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 179 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 10MHz / 16QAM

### 99% Occupied Bandwidth Plot on Channel 20000



Date: 7.JUN.2014 00:59:04

#### 26dB Bandwidth Plot on Channel 20000




Date: 7.JUN.2014 00:59:43

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 180 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:05:38


### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 01:06:17


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 181 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:08:56

### 26dB Bandwidth Plot on Channel 20350




Date: 7.JUN.2014 01:09:35

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 182 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 15MHz / QPSK

### 99% Occupied Bandwidth Plot on Channel 20025



Date: 7.JUN.2014 01:15:17

#### 26dB Bandwidth Plot on Channel 20025




Date: 7.JUN.2014 01:15:54

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 183 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:21:51


### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 01:22:28


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 184 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:25:09

### 26dB Bandwidth Plot on Channel 20325




Date: 7.JUN.2014 01:25:46

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 185 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 15MHz / 16QAM

### 99% Occupied Bandwidth Plot on Channel 20025



Date: 7.JUN.2014 01:15:35

#### 26dB Bandwidth Plot on Channel 20025




Date: 7.JUN.2014 01:16:13

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 186 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:22:09


#### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 01:22:48


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 187 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:25:27

### 26dB Bandwidth Plot on Channel 20325




Date: 7.JUN.2014 01:26:06

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 188 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 20MHz / QPSK

### 99% Occupied Bandwidth Plot on Channel 20050



Date: 7.JUN.2014 01:31:48

### 26dB Bandwidth Plot on Channel 20050




Date: 7.JUN.2014 01:32:27

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 189 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:38:25


### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 01:39:02


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 190 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:41:43

### 26dB Bandwidth Plot on Channel 20300




Date: 7.JUN.2014 01:42:20

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 191 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 4 BW / Mod.: 20MHz / 16QAM

### 99% Occupied Bandwidth Plot on Channel 20050



Date: 7.JUN.2014 01:32:07

#### 26dB Bandwidth Plot on Channel 20050




Date: 7.JUN.2014 01:32:47

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 192 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:38:43


### 26dB Bandwidth Plot on Channel 20175



Date: 7.JUN.2014 01:39:22


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 193 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 7.JUN.2014 01:42:01

### 26dB Bandwidth Plot on Channel 20300




Date: 7.JUN.2014 01:42:40

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 194 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 13 BW / Mod.: 5MHz / QPSK

### 99% Occupied Bandwidth Plot on Channel 23205



Date: 8.JUN.2014 12:05:52

#### 26dB Bandwidth Plot on Channel 23205




Date: 8.JUN.2014 12:06:30

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 195 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 12:07:08


#### 26dB Bandwidth Plot on Channel 23230



Date: 8.JUN.2014 12:07:46


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 196 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 12:08:23

#### 26dB Bandwidth Plot on Channel 23255




Date: 8.JUN.2014 12:09:01

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 197 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B


Band: LTE Band 13 BW / Mod.: 5MHz / 16QAM

### 99% Occupied Bandwidth Plot on Channel 23205



Date: 8.JUN.2014 12:06:10

#### 26dB Bandwidth Plot on Channel 23205




Date: 8.JUN.2014 12:06:50

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 198 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 12:07:26


#### 26dB Bandwidth Plot on Channel 23230



Date: 8.JUN.2014 12:08:05


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 199 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B



Date: 8.JUN.2014 12:08:41

#### 26dB Bandwidth Plot on Channel 23255



Date: 8.JUN.2014 12:09:21

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : 200 of 474
Report Issued Date : Oct. 07, 2014
Report Version : Rev. 01

Report No.: FG441109B