## **NetComm Wireless Limited**

Level 2, 18-20 Orion Road, 2066, Lane Cove, NSW, Australia Tel: +64(0)9 913 1708 ; Fax: +64(0)9 427 9260

Date: October 2, 2012

Federal Communications Commission Authorization and Evaluation Division 1435 Oakland Mills Road Columbia, MD 21046

SUBJECT: Supersede Request Letter

FCC ID: XIA-NTC40WV

Request for supersede of documents listed below:

NTC-40WV RFExp

NTC-40WV TestRpt DTS

NTC-40WV TestRpt PCB

The file name of the updated documents will be:

NTC-40WV RFExp 20121001update

NTC-40WV TestRpt DTS 20121001update.pdf

NTC-40WV TestRpt PCB 20121001update.pdf

Since the above-listed documents have shown wrong HW Version in test report, we are asking to replace the files.

Sincerely yours,

Contact Person: Casey Mak

Company: NetComm Wireless Limited

**TEL:** +64(0)9 913 1708 **FAX:** +64(0)9 427 9260

E-mail: caseym@netcomm.com.au