
3. Internal Photograph of EUT

Brand Name: NetComm / Model Name: 3G39W-V & 3G39W-I

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 6 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router

Report No.: EP102734




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W

Page Number : 7 of 15 Report Issued Date : Nov. 25, 2011

Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 8 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 9 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 10 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 11 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 12 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 13 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router


Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 14 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01

Marketing Name: HSPA+ Wi-Fi Router

Report No.: EP102734



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G39W IC: 8847A-3G39W Page Number : 15 of 15
Report Issued Date : Nov. 25, 2011
Report Version : Rev. 01