1. External Photograph of EUT

Brand Name: NetComm Wireless

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 1 of 27
Report Issued Date : Sep. 26, 2013
Report Version : Rev. 01

Report No.: EP380640

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 2 of 27
Report Issued Date : Sep. 26, 2013
Report Version : Rev. 01

Report No.: EP380640

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 3 of 27 Report Issued Date : Sep. 26, 2013

Report No.: EP380640

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 4 of 27
Report Issued Date : Sep. 26, 2013

Report No.: EP380640

notographs of EUT Report No.: EP380640

Brand Name: NetComm Wireless

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 5 of 27

Report Issued Date : Sep. 26, 2013

2. Photograph of Accessory

Brand Name: NetComm Wireless

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router

Specification of Accessory		
	Brand Name	N/A
	Model Name	N/A
	Signal Line	1.5 meter, non-shielded cable, without ferrite core
Docking	Brand Name	N/A
	Model Name	N/A
WWAN Antenna	Brand Name	Grand-Tek
	Model Name	OA-0314-11A6B0DNC
WWAN Module	Brand Name	Cinterion
	Model Name	PHS8-P

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 6 of 27
Report Issued Date : Sep. 26, 2013
Report Version : Rev. 01

Report No.: EP380640

Model Name: NWL-12-02

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1202 Page Number : 7 of 27 Report Issued Date : Sep. 26, 2013

Report No.: EP380640