

Appendix B. Setup Photographs

<Conducted Emission>



Front View



Rear View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G8WV Page Number : B1 of B4
Report Issued Date : Mar. 13, 2010

Report No.: FR022705

Report Version : Rev. 01



Report No.: FR022705



Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G8WV Page Number : B2 of B4
Report Issued Date : Mar. 13, 2010
Report Version : Rev. 01







<Radiated Emission>



Front View





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G8WV

Page Number : B3 of B4 Report Issued Date: Mar. 13, 2010 Report Version : Rev. 01

Report No.: FR022705





Report No. : FR022705



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G8WV Page Number : B4 of B4
Report Issued Date : Mar. 13, 2010
Report Version : Rev. 01