3. Internal Photograph of EUT

Brand Name: NetComm Wireless / Model Name: NWL-12-01


Marketing Name: 3G Light Industrial M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 8 of 31

Report No.: EP373184

Report Issued Date : Oct. 08, 2013 Report Version : Rev. 01



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 9 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 10 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

hotographs of EUT Report No.: EP373184

Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 11 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Report No.: EP373184


Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 12 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01


Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 13 of 31
Report Issued Date : Oct. 08, 2013

Report No.: EP373184


Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 14 of 31
Report Issued Date : Oct. 08, 2013

Report No.: EP373184


Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 15 of 31
Report Issued Date : Oct. 08, 2013


Report No.: EP373184

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 16 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 17 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Report No.: EP373184

Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 18 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

otographs of EUT Report No.: EP373184


Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 19 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 20 of 31
Report Issued Date : Oct. 08, 2013


: Rev. 01

Report Version

otographs of EUT Report No.: EP373184


Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 21 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 22 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01


Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 23 of 31
Report Issued Date : Oct. 08, 2013

Report No.: EP373184

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 24 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 25 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 26 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 27 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Report No.: EP373184

Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 28 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

Marketing Name: 3G Light Industrial M2M Router




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 29 of 31
Report Issued Date : Oct. 08, 2013
Report Version : Rev. 01

otographs of EUT Report No.: EP373184


Brand Name: NetComm Wireless / Model Name: NWL-12-01

Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 30 of 31
Report Issued Date : Oct. 08, 2013

Brand Name: NetComm Wireless / Model Name: NWL-12-01 Marketing Name: 3G Light Industrial M2M Router



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NWL1201 Page Number : 31 of 31
Report Issued Date : Oct. 08, 2013

Report No.: EP373184