
3. Internal Photograph of EUT

Brand Name: NetComm / Model Name: NHD1W / Marketing Name: NHD1W

Report No.: EP213125




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W Page Number : 9 of 16
Report Issued Date : Apr. 05, 2012
Report Version : Rev. 01



Brand Name: NetComm / Model Name: NHD1W / Marketing Name: NHD1W

Report No.: EP213125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W


Page Number : 10 of 16 Report Issued Date : Apr. 05, 2012 Report Version : Rev. 01



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W Page Number : 11 of 16
Report Issued Date : Apr. 05, 2012
Report Version : Rev. 01





SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W Page Number : 12 of 16 Report Issued Date : Apr. 05, 2012 Report Version : Rev. 01



Brand Name: NetComm / Model Name: NHD1W / Marketing Name: NHD1W

WLAN Antenna 1 <Tx / Rx>

80

70

60

50


40

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W Page Number : 13 of 16
Report Issued Date : Apr. 05, 2012
Report Version : Rev. 01

Report No.: EP213125





Report No.: EP213125




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W

Page Number : 14 of 16 Report Issued Date : Apr. 05, 2012 Report Version : Rev. 01



Brand Name: NetComm / Model Name: NHD1W / Marketing Name: NHD1W

Report No.: EP213125




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W Page Number : 15 of 16
Report Issued Date : Apr. 05, 2012
Report Version : Rev. 01



Brand Name: NetComm / Model Name: NHD1W / Marketing Name: NHD1W

Report No.: EP213125



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W IC: 8847A-NHD1W

Page Number : 16 of 16 Report Issued Date : Apr. 05, 2012 Report Version : Rev. 01