

# Appendix A. Setup Photographs

## <Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : A1 of A2
Report Issued Date : Feb. 11, 2015
Report Version : Rev. 02

Report No.: FR441109-03


Report Template No.: BU5-FR15CWL MA Version 1.0




### <Radiated Emission>

### Antenna Degree 0

LF



HF



#### SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : A2 of A2
Report Issued Date : Feb. 11, 2015
Report Version : Rev. 02

Report No.: FR441109-03

Report Template No.: BU5-FR15CWL MA Version 1.0