

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W

Page Number : B1 of B3 Report Issued Date: Apr. 05, 2012

Report No.: FR213125

Report Version : Rev. 01




Report No. : FR213125


<Radiated Emission>

Mode 1~5 and 7~15

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W Page Number : B2 of B3
Report Issued Date : Apr. 05, 2012
Report Version : Rev. 01






Mode 6

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NHD1W Page Number : B3 of B3
Report Issued Date : Apr. 05, 2012
Report Version : Rev. 01

Report No.: FR213125