3. Internal Photograph of EUT

Brand Name: NetComm Wireless

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 8 of 19 Report Issued Date : Sep. 26, 2012

Report No.: EP253048

Report Version : Rev. 02

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 9 of 19 Report Issued Date : Sep. 26, 2012

Report No.: EP253048

Report Version : Rev. 02

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 10 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

Report No.: EP253048

Brand Name: NetComm Wireless

Model Name: 3G22WV


Marketing Name: HSPA+ WiFi Router with Voice



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 11 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 12 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 13 of 19
Report Issued Date : Sep. 26, 2012

Report No.: EP253048

Report Version : Rev. 02

Model Name: 3G22WV


Marketing Name: HSPA+ WiFi Router with Voice



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 14 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

Model Name: 3G22WV


Marketing Name: HSPA+ WiFi Router with Voice



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 15 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 16 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

otographs of EUT Report No.: EP253048

Brand Name: NetComm Wireless

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 17 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02



Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 18 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02

Report No.: EP253048

Brand Name: NetComm Wireless

Model Name: 3G22WV

Marketing Name: HSPA+ WiFi Router with Voice



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-3G22WV IC: 8847A-3G22WV Page Number : 19 of 19
Report Issued Date : Sep. 26, 2012
Report Version : Rev. 02