Appendix A. Setup Photographs

<Conducted Emission>



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : A1 of A2
Report Issued Date : Oct. 09, 2014
Report Version : Rev. 01


Report No. : FR441109

Report Template No.: BU5-FR15CWL Version 1.0 Report Template No.: BU5- CR210WL Version 1.0


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: XIA-NTC140W IC: 8847A-NTC140W Page Number : A2 of A2
Report Issued Date : Oct. 09, 2014
Report Version : Rev. 01

Report No. : FR441109

Report Template No.: BU5-FR15CWL Version 1.0 Report Template No.: BU5- CR210WL Version 1.0