
Internal Photographs Lord Corporation FCC ID: XJQMSLINK0012 / IC: 8505A-MSLINK0012



Top of PCB

Internal Photographs Lord Corporation FCC ID: XJQMSLINK0012 / IC: 8505A-MSLINK0012



Top of PCB (Battery Holder Removed)


Internal Photographs Lord Corporation FCC ID: XJQMSLINK0010 / IC: 8505A-MSLINK0010



Bottom of PCB



Internal Photographs Lord Corporation FCC ID: XJQMSLINK0010 / IC: 8505A-MSLINK0010



Bottom of PCB, RF Shield Removed