



112920\_3.JPG: TX-RX01 with internal antenna, test setup fully anechoic chamber (Pos. 1)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 1 of 11





112920\_2.JPG: TX-RX01 with internal antenna, test setup fully anechoic chamber (Pos. 2)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 2 of 11





112920\_4.JPG: TX-RX01 with internal antenna, test setup fully anechoic chamber (Pos. 3)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 3 of 11





112920\_8.JPG: TX-RX01 with external antenna, test setup fully anechoic chamber (Pos. 1)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 4 of 11





112920\_6.JPG: TX-RX01 with external antenna, test setup fully anechoic chamber (Pos. 2)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 5 of 11






112920\_9.JPG: TX-RX01 with external antenna, test setup fully anechoic chamber (Pos. 3)

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 6 of 11






112920\_11.JPG: TX-RX01, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 7 of 11





112920\_13.JPG: TX-RX01, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 8 of 11






112920\_1.JPG: TX-RX01, test setup fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920
 page 9 of 11





112920\_22.JPG: TX-RX01, test setup open area test site

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920

 page 10 of 11
 page 10 of 11





112920\_39.JPG: TX-RX01, test setup shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F112920E1

 Date of issue:
 05 October 2011
 Order No.:
 11-112920

 page 11 of 11
 page 11 of 11