INTERNATIONAL TECHNICAL MKTG. INC.

FCC ID: XLTKTUS-1L

TUNING PROCEDURE

Re: XLT-KTUS-1L Field Tune Up Procedure

Due to the remote locations in which this product is used, as well as the complications of servicing at sea while maintaining a good ground plane, we do not recommend field servicing. Experience has shown that the cost of replacement PCB's, antenna parts etc. are far less than the man hour cost required to trouble shoot and then repair the PCB's. Our customers will be far better served by replacing modules rather than making field repairs. ITM Marine has had this policy for this product type for the last 18 years with success.