

Report No.: FR741007B

Appendix D. Setup Photographs

<Conducted Emission>



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XMR201706SC20A


Page Number : D1 of D2 Report Issued Date : Aug. 11, 2017 Report Version : Rev. 01 Report Template No.: BU5-FR15CBT4.0 Version 2.0




Report No.: FR741007B

<Radiated Emission>

LF



HF



Sporton International (KunShan) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: XMR201706SC20A Page Number : D2 of D2
Report Issued Date : Aug. 11, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 2.0