
Appendix C. Setup Photographs


<Radiated Emission>

For 22H

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: XMR201901EM12G Page Number : C1 of C2
Report Issued Date : Jan. 30, 2019
Report Version : Rev.01

Report No.: FG8N2911A

Report Template No.: BU5-FG22/24/27 Version 2.0




For 24E, 27L

LF



HF



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: XMR201901EM12G Page Number : C2 of C2
Report Issued Date : Jan. 30, 2019
Report Version : Rev.01

Report No. : FG8N2911A

Report Template No.: BU5-FG22/24/27 Version 2.0