
# Appendix C. Setup Photographs


## <Radiated Emission>

for Band 2, 5, 7

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: XMR201905AG35LA Page Number : C1 of C2
Report Issued Date : Jun. 26, 2019
Report Version : Rev. 01


Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG932502B


### <Radiated Emission>

#### for Band 4

LF



#### HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: XMR201905AG35LA Page Number : C2 of C2
Report Issued Date : Jun. 26, 2019
Report Version : Rev. 01

Report Template No.: BU5-FGLTE Version 2.0

Report No.: FG932502B