
Appendix C. Setup Photographs


<Radiated Emission>

For 22H

LF



HF



Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: XMR201905AG35LA Page Number : C1 of C2
Report Issued Date : Jun. 26, 2019
Report Version : Rev. 01


Report No.: FG932502A

Report Template No.: BU5-FG22/24/27 Version 2.0


<Radiated Emission>

For 24E, 27L

LF



HF



TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: XMR201905AG35LA Report No.: FG932502A

Report Template No.: BU5-FG22/24/27 Version 2.0