


View of inside





Top side view of main board #1




Report no. ETLE090805.02, Page D2 of D18

Top side view of main board #2



Report no. ETLE090805.02, Page D3 of D18


Bottom side view of main board



Report no. ETLE090805.02, Page D4 of D18




Top side view of 802.11b/g main board



Report no. ETLE090805.02, Page D5 of D18



Bottom side view of 802.11b/g main board



Report no. ETLE090805.02, Page D6 of D18


Top view of TUNER board (A)



Report no. ETLE090805.02, Page D7 of D18




Top view of TUNER board (A) - Internal



Report no. ETLE090805.02, Page D8 of D18

Bottom view of TUNER board (A)




Report no. ETLE090805.02, Page D9 of D18

Top view of TUNER board (B)




Report no. ETLE090805.02, Page D10 of D18

Top view of TUNER board (B) - Internal




Report no. ETLE090805.02, Page D11 of D18

Bottom view of TUNER board (B)



Report no. ETLE090805.02, Page D12 of D18


Top view of Front board



Report no. ETLE090805.02, Page D13 of D18




Bottom view of Front board



Report no. ETLE090805.02, Page D14 of D18




Top side view of Smart card board



Report no. ETLE090805.02, Page D15 of D18




Bottom side view of Smart card board



Report no. ETLE090805.02, Page D16 of D18




Top side view of USB board



Report no. ETLE090805.02, Page D17 of D18



Bottom side view of USB board



Report no. ETLE090805.02, Page D18 of D18