

170297_E6_01.jpg: Test setup – antenna port conducted measurements

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

 page 1 of 7
 page 1 of 7






170297_E6_02.jpg: Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

 page 2 of 7
 page 2 of 7





170297_E6_03.jpg: Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

 page 3 of 7
 page 3 of 7





170297_E6_04.jpg: Test setup open area test site

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

page 4 of 7






170297_E6_05.jpg: Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

page 5 of 7






170297_E6_06.jpg: Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

page 6 of 7





170297_E6_07.jpg: Test setup fully anechoic chamber

 Examiner:
 Bernward ROHDE
 Report Number:
 F170297E6

 Date of issue:
 26.02.2018
 Order Number:
 17-110297

page 7 of 7